P: Is this is probably yours.

B: It might be, I was more at an angle.

B: I think I hit him.

B: I think might be Manny's.

B: Manny was down rolling with him trying to do drive-stun him.

B: That doesn't look, that looks like That one went straight into the fence. My shit would have been more at an angle.

P: So you were here

B: I was right in this area.

B: He was back, he was back against the fence when I tasered him _____ So it could have been.



Ciampi's left leg is at the edge of the sidewalk touching the ivy.
Burger's left leg in the ivy just before the sidewalk.
Burger's right leg is also in the ivy just before the sidewalk.

Ciampi and Burger are separated by a minimum of THREE FT. (3'ft). parallel to the sidewalk. That is Ciampi is 3ft. further west down the sidewalk closer to Temore' MAV camera than Burger.



CONCLUSION:

Officer Burger fired his taser gun from a location two to three feet above where the taser probe lodged into the fence.

Officer Burger fired his probes at an angle away from the location where the taser probe lodged into the fence.

Officer Burger fired his probes to the fron side of Ciampi, yet the probe in the fence is behind Ciampi. It would be physically impossibly for a taser probe to lodge into the fence behind Ciampi given the angle at which Burger fired his taser gun.

Officer Burger himself stated that he fired his taser gun at an angle which would not have ended up in the fence at the location which the taser probe is lodged.

Based upon the video footage provided by the Palo Alto Police, neither of the taser probes from Officer Burger's taser gun could have lodged into the fence at the location which a taser probe lodged into the residential fence.

Ofc. Temores removing evidence from the crime scene prior to photographs being taken.

Ostensibly this is his expended taser cartridge which the Palo Alto Police have admitted to destroying. Temores testified that his cartridge broke. The PAPD didn't even take a picture of it.

TEMORES' MAV



TEMORES' TASER VIDEO

The 10:10:45,46 & 47 mark of Temores' MAV video corresponds to the :04 Mark of Temores' Taser video.

Three minutes after recording the below image onto his Taser camera, Ofc. Temores is seen picking up a taser probe/cartridge from the exact spot where there is an unus



The taser probe/cartridge is not recorded on Temores' taser video. It appears as if the taser probe/cartridge has been removed from the taser video by using an editing technique of moving the ivy to cover it up.

Q. Did you collect any, um, evidence at the scene?
A. I believe I did, yes.
Q. What evidence did you collect?
A. I believe it was a -- just my taser cartridge, which I dropped on the floor after taking it off from my taser.
Q. You say dropped on the floor. Do you mean on the ground?
A. On the ground.
Q. On the sidewalk?
A. Yes.
Q. Did it break?
A. Yes, it did.
Q. And you didn't collect any other evidence?

A. No, I don't believe so.
Q. Did you see a cell phone on the sidewalk?
A. I don't remember.

Q. Okay. Could you tell us what happened to your cartridge.
A. Which one? I have two.
Q. Well, the cartridge to your taser gun that broke.
A. Yes. Before I -- before I, uh -- well, what I did was I took it off and dropped it on the ground, so --
Q. By accident?
A. No; purposely.
Q. Is that when it broke?
A. I'm not sure when it broke, but I believe it must have. It hit a hard surface.
Q. Okay. Is that in evidence?
A. I'm not sure.
Q. Well, did you turn over evidence to the officers that control the property room?

A. I don't have my report in front of me, and I don't recall --
Q. Okay.
A. -- whether I did or not.

The Palo Alto Police took photographs of one taser cartridge, two taser probes, two blast doors, Temores' taser gun with a new taser cartridge attached, blood on Temores and his taser gun, broken sunglasses, and a broken bicycle helmet, yet the PAPD DID NOT take a photograph of Temores' broken taser cartridge,